



Family Jewel



46'6" (14.2 m) BERTRAM

LOA:	46'6" (14.2 m)	Year:	Mfg-1987 Model-1987
Beam:	16' (4.9 m)		Refit-2010
Draft:	Min 4' (1.2 m)	Mfg:	BERTRAM
Speed:	/ 27 knots	Type:	Sport Fisherman
Location:	Hallandale, FL, United States		Sport Fisherman
		Price:	195,000 USD

[Andy Kniffin CPYB|\(954\) 292-0629 USA|andy@akyachts.com|www.akyachts.com](mailto:andy@akyachts.com)

Family Jewel

Page 1

Additional Specifications For Family Jewel:

LOA:	46'6" (14.2 m)	Year:	Mfg-1987 Model-1987
Mfg. Length:			Refit-2010
Beam:	16' (4.9 m)	Mfg:	BERTRAM
Draft:	Min 4' (1.2 m)	Model:	Mark III
Hull Mtrl:	Fiberglass	Type:	Sport Fisherman
Hull Cnfg.:	Modified V-Hull		Sport Fisherman
Hull Designer:		Top:	With Flybridge
Deck Mtrl:	Fiberglass		Half Tower
Disp:		Speed:	/ 27 knots
Range:		Engines:	2xDetroit Diesel
Flag:	US		8V92
Location:	Hallandale, FL, United States		735 HP
			SMOH - 500 hrs
		Engines Year:	
		Fuel Cap:	750 g (2839 l)
		Water Cap:	250 g (946 l)
		Holding Tank:	
		Staterooms:	2
		Sleeps:	4
		Heads:	2
		Price:	195,000 USD

Accommodations

Entering the spacious salon, a large L-shaped sofa is to port with a coffee table and two easy chairs, entertainment console to starboard. The windows have mini-blinds. Note that the entire interior is paneled in rich, dark oakwood. "Family Jewel" was recently re-carpeted with a beige pile carpet, new drapery and bedspreads. Moving to starboard and forward is a galley, then a twin-bunk guest stateroom with a private bath and a master stateroom forward with a centerline queen bed and private bath.

Galley

The galley is down and features an L-shaped mica countertop with teak parquet flooring.

Amana full-sized fridge/freezer (2006)
Quasar microwave/convection oven
3-burner stove
Garbage disposal
Washer/Dryer
Raritan icemaker (salon)(2008)

[Andy Kniffin CPYB|\(954\) 292-0629 USA|andy@akyachts.com|www.akyachts.com](mailto:andy@akyachts.com)

Family Jewel

Page 2

Engine Room & Mechanical

Racor fuel/water separators
Morse engine controls
(4) Automatic bilge pumps
CO2 fire suppression system
Handheld fire extinguishers
Crusair reverse cycle air conditioning system (compressors renewed 2003 w/smx digital controls)
Water pressure system (well-pump type 2010 and Galleymaid 32vdc pump w/accumulator tank)
Water heater
Galleymaid heads (2006 motors replaced)

Electronics and Entertainment

Garmin GSmap 440 gps plotter
Datamarine depth/knot log
Furuno radar (24 nm)
Roberson 200 DL autopilot
Furuno 585 FCV video sounder
Icom M700 vhf radio (2010)
Ritchie compass
Stereo system (FB) (new speakers 2010)
TV's salon and msr
CD, DVD, Stereo system in salon (plays throughout boat)

Hull & Deck Equipment

The flybridge is accessed via a ladder with FRP steps. It features a semi-rigid aluminum framed top with a 3-sided enclosure (renewed 2010), a plexiglass venture windscreen (nice condition), two Stidd helm chairs and a bench seat with cushion forward. The exterior gelcoat gleams and has always been cared for. A custom set of spray rails help the performance. The bottom was repainted in 2010 along with propspeed for the running gear.

Forward deck davit and 11' Boston whaler with Evinrude 20 hp outboard engine (2 cycle) on Marquipt chocks (also pwc chocks interchangeable, new cover for whaler 2010)

Outriggers
Windlass with chain and anchor
Tackle center
International fighting chair (refinished 2010)
Transom fish box (with cushion)
Livewell
Rod holders – cockpit and flybridge
Custom FRP side-panels in cockpit with storage
Folding steps on either side cockpit

[Andy Kniffin CPYB|\(954\) 292-0629 USA|andy@akyachts.com|www.akyachts.com](mailto:andy@akyachts.com)

Family Jewel

Page 3

Aft partial bimini top over cockpit – a full-sized bimini top zips onto this
Dual trumpet horn
Spare propellers
Spare shaft
(4) bow fender holders with fenders
Docklines
Forward windshield textyline cover

Electrical System

Northern lights 12kw genset (850 hours) (under cockpit with soundshield)
Sentry battery chargers (2010)
2 banks of 8D batteries (32vdc) (2010)
Genset battery (2010)
Battery disconnect switches
VAC/VDC distribution panel
Cockpit outlets for electric reels
Interior and exterior lighting
Navigation lighting
Remote spotlight
Aft floodlight
Engine room blowers
(2) 25' and single 50' 50amp shore cables

Remarks

This fine 46' Bertram Mark III model (restyled interior and centerline queen forward) has been lovingly cared for by an original owner. Her gelcoat gleams as new and all systems work well. Note the engines were overhauled approximately 500 hours ago and the genset was upgraded to a Northern Lights 12kw model with a soundshield. An 11' Boston Whaler complements the boat. Newly renovated interior soft goods including carpet, drapes and shams.

The 46' Bertram has always been a classic design for a sportfisher and is a proven seakeeper. Savvy buyers recognize that the best boats are the ones that have been well-cared for..."Family Jewel" is sure to impress even the fussiest buyers.

Disclaimer

The Company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change, or withdrawal without notice.

Salon



Salon



Andy Kniffin CPYB|(954) 292-0629 USA|andy@akyachts.com|www.akyachts.com

Family Jewel

Page 5

Galley



Master stateroom



[Andy Kniffin CPYB|\(954\) 292-0629 USA|andy@akyachts.com|www.akyachts.com](mailto:andy@akyachts.com)

Family Jewel

Page 6

Guest stateroom



Flydbridge



Andy Kniffin CPYB|(954) 292-0629 USA|andy@akyachts.com|www.akyachts.com

Family Jewel

Page 7

Flybridge settee



cockpit



Andy Kniffin CPYB|(954) 292-0629 USA|andy@akyachts.com|www.akyachts.com

Family Jewel

Transom



Engine room



Andy Kniffin CPYB|(954) 292-0629 USA|andy@akyachts.com|www.akyachts.com

Family Jewel

Page 9